Clothes with integrated belt-system

Fire Protec® Belt Jacket, Bozen

- absolutely waterproof and breathable cause of GORE-TEX® membrane
- flame retardant TEXPORT® absorption barriers on sleeves, jacket seam and front strip, prevents permanently the ingress of moisture
- extreme reduction of weight, raised breathability and very fast drying cause of GORE-TEX® Airlock® Spacer Technology
- repair-zip in inner-lining to realize quick and cost-saving repairs
- hanging-up loops in the collar
- resistant against dry cleaning
- inside pocket right

Specification:

Item no.:	**1172001A1**
Certified after:	**EN 469:2005, Xf2, Xr2, Y2, Z2; EN 1149-3, EN 358 (belt)**
Structure:	**Liner construction**
Upper material:	**Nomex® Tough™**
Membrane:	**GORE-TEX® Airlock® Spacer Technology**
Lining:	**Nomex®/Viskose FR**
Reflecting mat.:	**3M Scotchlite™ silver and persistent sipi-yellow**
Colour:	**darkblue**
Sizes:	**S- XXL**

- **Patented HPX system®** in the front bar area allows rapid, simple and cost-effective replace a faulty zipper. The repair costs are reduced over the years to a minimum

- integrated waist belt, the exit of the belt in the front is covered with flaps

Texport® GmbH · Franz-Sauer-Straße 30 · A-5020 Salzburg
email: office@texport.at · www.texport.at

TEXPORT® functionals
...protecting you

Clothes with integrated belt-system

Fire Protec® Trousers, Südtirol

Specification:

Item no.:	**1201101D1**
Certified after:	**EN 469:2005, Xf2, Xr2, Y2, Z2; EN 1149-3**
structure:	**Liner construction**
upper material:	**Nomex® Tough™**
membrane:	**GORE-TEX® Airlock® Spacer Technology**
lining:	**Nomex®/Viskose FR**
reflecting mat.:	**3M Scotchlite™ silver and persistent sipi-yellow**
colour:	**darkblue**
sizes:	**S-XXL**

- absolutely waterproof and breathable cause of GORE-TEX® membrane
- flame retardant TEXPORT® absorption barriers on trousers seams prevents permanently the ingress of moisture
- repair-zip in inner-lining for quick and cost-saving repairs
- extreme reduction of weight, raised breathability and very fast drying cause of GORE-TEX® Airlock® Spacer Technology
- resistant against dry cleaning
- hanging-up loops at the waist

Subject to modifications and misprints!

Texport® GmbH · Franz-Sauer-Straße 30 · A-5020 Salzburg
email: office@texport.at · www.texport.at

TEXPORT® functionals ...protecting you